
WASHINGTON
Klickitat County
Roosevelt
14
Sundale
Columbia River
Arlington
84
19
Slatt Substation
OREGON
Gilliam County
Long Canyon
Jones Canyon
China Creek
Jones Canyon Substation
19
Proposed BPA Interconnection of Leaning Juniper III Wind Farm
Leaning Juniper III Wind Farm
BPA Substation
BPA Transmission Lines
County Boundary
0 0.5 1 2 Miles
GIS · PHOTOGRAMMETRY · REMOTE SENSING
GEOSPATIAL SERVICES
JJB Dec. 2008
N
WA
Portland
Project Area
OR