Figure 3-15
Viewpoint 4: View to the south near the intersection of Highway 2 and Highway 56 (Bull Lake Road) of Alternative 1

Existing Condition (The Proposed Action would look similar to the existing condition)

With photo simulation of Alternative 1