



# REBUILD OF THE LIBBY TO TROY SECTION OF BPA'S LIBBY TO BONNERS FERRY 115-KILOVOLT TRANSMISSION LINE

## LAND TYPES



- |                            |   |
|----------------------------|---|
| ▲ Substation               | <span style="display: inline-block; width: 15px; height: 15px; background-color: yellow; border: 1px solid black;"></span> Glacial Outwash Terraces |
| ● Corridor Mile Marker     | <span style="display: inline-block; width: 15px; height: 15px; background-color: purple; border: 1px solid black;"></span> Lacustrine Terraces      |
| --- Potential Realignment  | <span style="display: inline-block; width: 15px; height: 15px; background-color: green; border: 1px solid black;"></span> Glaciated Mountain Slopes |
| — Proposed Rebuild Section | — Other Transmission Lines  |

Data Source: Kootenai National Forest GIS Library.  
 Bonneville Power Administration Regional GIS Database.  
 All Data Is Best Available, 12/1/2006



Figure 3-1